

HITACHI Inspire the Next

Hitachi High-Tech Analytical Science

2 Technology Park Drive, 2nd Floor Westford, MA 01886, USA

Tel: +1 (888) 580 8070. Fax: +1 (978) 303 0002 Email: support.us@hitachi-hightech-as.com

www.hitachi-hightech.com/hha

Work Details

Case Number

00084565

Work Order

WO-00058115

Number

Appointment

SA-8259

Number

Material

X-SUPREME CONFIGURED AVC

Installed Unit

Start Date

End Date

X20035

10/14/2020 8:08 AM

Account & Contact Information

Account

OLEIN RECOVERY CORPORATION

Work Type

Installation

Category

Address

Carr 3 Km 90.4 Bo Aguacate,

.

Coverage

PO Number

Warranty

Warranty

Contact for FSR

Puerto Rico Yolanda Rivas

Phone: 787-266-2103

YABUCOA 00767

Email: yrivas@oleincorp.com

Fax:

Summary of Work

Subject

INSTALLATION

Instrument Status

Fully Working

Instrument Environment

Service Note

Completed X-Supreme install and trained operator.

Info for Config Update (900 series only)

Current Ag

Counts

X-Ray Tube Time at Full Current

AG FWHM

HASP/SW Expiration Date

(FP)

AG Peak

Environment

Good

Rules File (FP)

Material Used and Estimated Cost

The following parts and material were included above as part of this work order's line item detail. They are broken out in this section for quick reference.



Hitachi High-Tech Analytical Science

2 Technology Park Drive, 2nd Floor Westford, MA 01886, USA Tel: +1 (888) 580 8070. Fax: +1 (978) 303 0002 Email: support.us@hitachi-hightech-as.com www.hitachi-hightech.com/hha

> Total Price to Invoice

The total estimated cost of this visit is detailed on this service order and my signature below indicates I understand and accept responsibility for these charges on behalf of the company listed above. The Address above is correct for Billing and any exceptions or objections have been noted in the customer comments section below. Additional charges for Taxes and Shipping may be added to this estimate. If you are a tax exempt company, please specify tax exemption number.

Parts to Return

Failure to return the unused parts will result in additional charges.

Product Code, Name

Quantity to Return

Part Status

Tracking Number, Required Parts

Carrier, Return

FedEx

Parts

Customer Signature

Signature

Guttrer

Signed By

Grace M. Bultrón Rodriguez

Date

10/15/2020 11:31 AM

Type

Customer

Service Engineer Signature

Signature

Signed By Cyrus

Date

10/15/2020 11:30 AM

Туре

Service Engineer

Radiation Leakage Survey